

**FORMER CLIFF DOW SITE**  
WRIGHT ST. & LAKESHORE BLVD, MARQUETTE, MICHIGAN

---



Date: 8/20/09

Taken By: TAG

Description: SS-2 Fill and charcoal debris



Date: 8/20/09

Taken By: TAG

Description: SS-2 Charcoal debris

**FORMER CLIFF DOW SITE**  
WRIGHT ST. & LAKESHORE BLVD, MARQUETTE, MICHIGAN

---



Date: 8/20/09

Taken By: TAG

Description: SS-4 Small tar deposit and debris



Date: 8/20/09

Taken By: TAG

Description: SS-4 Small tar deposit and debris

**FORMER CLIFF DOW SITE**  
WRIGHT ST. & LAKESHORE BLVD, MARQUETTE, MICHIGAN

---



Date: 8/20/09  
Description: SS-26 Tar deposit

Taken By: TAG



Date: 8/20/09  
Description: SS-26 Tar deposit

Taken By: TAG

**FORMER CLIFF DOW SITE**  
WRIGHT ST. & LAKESHORE BLVD, MARQUETTE, MICHIGAN

---



Date: 8/25/09

Taken By: DDM

Description: SB-2 Tar sand mix on sleeves



Date: 8/25/09

Taken By: DDM

Description: SB-2 Tar sand mix on drilling rod

**FORMER CLIFF DOW SITE**  
WRIGHT ST. & LAKESHORE BLVD, MARQUETTE, MICHIGAN

---



Date: 8/25/09

Taken By: DDM

Description: SB-2 Tar sand mix on drilling rod



Date: 8/25/09

Taken By: DDM

Description: Typical fill and debris in borings